








Work Order: 39725
Last Name: SARTIN
Registration: V2BSY
Technician: LA
Odometer: 31363
Date: 15.7.22 14:32

Porsche : 911 : 991 (2012-16) : Carrera 4/4S PASM 4-Wheel Total Alignment



• One or more values are not within specification. Tyre wear, handling and safety problems may result.

Your tyres. Reg No: V2BSY Booking No: 39725

Tyres		What does this mean?		Visually OK	Advisory	Immediate attention	
Front Right		Front Left		Rear Right		Rear Left	
	23 % worn		27 % worn				
	6.5 mm		6.3 mm				
	pressure checked		pressure checked				
	6.5 inner tread depth		6.3 inner tread depth				
	6.9 middle tread depth		6.6 middle tread depth				
	6.5 outer tread depth		6.8 outer tread depth				
Comments		Comments		Comments		Comments	
						Canister - Expired	

Please note: This report and any repair costs shown are the result of a visual inspection only. Further checks may be necessary to determine the full extent of any requirements. Parts subject to wear are considered defective when the maximum amount of wear permissible is reached.

Tyre labelling

What does it all mean?

All tyres now come with a label that gives ratings for fuel efficiency, wet grip and rolling noise. In the case of fuel efficiency, a rating of A indicates the most efficient and G the least. For wet grip, a tyre with an A rating provides the shortest braking distance and G, the longest. Finally, external rolling noise is measured in decibels. One wave indicates a quieter tyre and three waves are louder (when comparing identical section widths).